



As of 9/2003, the current software revision is 4.1

- Hytron 50 / Hytron 100
  - Requires software revision 3.2 or higher
    - Any QUAD with a serial# of 8000 or higher (serial# below will not work)
    - Any Lifesaver DUAL charger
    - Any "InterActive 2000" Power Charger
    - Any MP4-D Logic Series Charger
    - Any MP-2 Charger
    - Any XM2002/2004 Charger Module
    - Any ABC-800 Charger
  
- Hytron 120
  - Requires software revision 3.2 or higher
    - Any QUAD with a serial# of 8000 or higher (serial# below will not work)
    - Any Lifesaver DUAL charger
    - Any "InterActive 2000" Power Charger
    - Any MP4-D Logic Series Charger
    - Any MP-2 Charger
    - Any XM2002/2004 Charger Module
    - Any ABC-800 Charger
  
- Dionic (Dionic80 or Dionic90)
  - Any InterActive 2000 Power Charger (with software revision 3.6 or higher)
  - TitanTwin (two-tone model only)
  - TitanT2
  - Titan70 with a serial# of 1033 or higher (serial# below must be upgraded at factory)

**Rated Amp Hours By Battery Type**

<b>Model</b>	<b>Amp Hours for Capacity Testing (calc: watts/14.4VDC=Ah)</b>	<b>Rated Watts</b>
Dionic90	? (6.2)	90
Dionic80	? (5.7)	80
Hytron100	6.7 (6.9)	100
Hytron120	8.5 (8.3)	120
Hytron50	3.5 (3.5)	50
DPP14/PP14	4.0 (4.5)	65
DTP14/TP14	? (3.1)	45
ProFormer	? (2.1)	30